

Renewal $\frac{1}{4}$ SE only T308 R1W

Found:

17" cedar New 22" N56W 31 $\frac{3}{4}$
shows good scar

10" cedar New 17" S43W 4 $\frac{1}{2}$
shows good scar

Also cor stone at $\frac{1}{4}$ cor MAD $\frac{1}{4}$

Renewal

This cor should be for SE
only therefore set Brass cap
at $\frac{1}{4}$ cor MAD

County Surveyors office

T308 R1W

$\frac{1}{4}$ SE

1968

DIETZGEN NO. 385-6

New Bearing Trees

8" Maple N48W 19 $\frac{3}{4}$
Scribed $\frac{1}{4}$ SE cor BT

O.B.T.

22" cedar N56W 31 $\frac{3}{4}$
OK & Jagged

Note:

I do not destroy SW BT for
control purposes.

Also cor lies on NE slope
approx 100 $^{\circ}$ East of Ridge Tip

7-18-68

~~_____~~
~~_____~~

#79

O.K. J.W.B.

C.S. File No. 54/59-125