

Renew Closing Cor. $\frac{59}{516}$ T225 R9W

Fd. $1\frac{1}{2}$ " I.P. & BRASS cap at cor point

Mkd. $\frac{59}{516}$ 510" \pm 1870 BT'S as follows -

8" Now 30" W. FIR N. 65° E 53 $\frac{1}{2}$ ft.

Now sawed stump - we open top of stump
& find Reverse Scribe MKs.

30" Now 48" FIR S. 40° W. 121 $\frac{1}{4}$ ft.

Now shattered stump - shows old scar.

8" Now 28" W. FIR N. 21° W. 116 $\frac{1}{4}$ ft.

Record. 97 $\frac{1}{2}$ ft. - Now snag - previously
opened & shows "S 9" scribe.

at cor. point in place of unrecorded
pipe set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYOR'S OFFICE 1968

T225 C. $\frac{59}{516}$ R9W" & MK. New BT'S -

7" Alder S. 45° W. 57 $\frac{1}{2}$ ft.

Mkd. "T225 R9W 516 C C C S BT"

13" D. FIR N. 84° W. 68 $\frac{1}{2}$ ft.

Mkd. "T225 R9W 59 C C C S BT."

This cor. lies on gentle E. slope
in old logged off area. Reset old pipe
along side BRASS cap.

June 24, 1968

G.R.T.
V.H.
V.P.

G.R. Tracy
#66

(see over)
C.S. No. 546
S.W. 6

Fd T225 R9W

at a point 181⁰ ft South of
CC, on Reverse side, we find
a 1 1/2" I.P. of Brazed cap MKd 5/16" 5/15"
UNRECORDED - we find no Q.B.T.
To jibe with this pipe or at the
Record distance of 2079 ft. S. of
C.C. COR. - also Canon Creek does
not fit the Record distance
we do not Renew - 6/24/08

by R. J. Tracy

V.R.
J.H.
V.P.

DIETZEN NO. 385-6

D.K.M. J.W.B.