

Renew $\frac{59}{516}$ T235 R9W

Fd. 1st E.P. 2nd cor. (unrecorded)

set from stumps of apparent
O.B.T.'s 25 follows -

Orig. 50" Now 60" Fir N. 17° E, 38 $\frac{1}{2}$ ft,

Now stump - No Bark - No Scribe Fd.

Orig 60" Now 64" Fir S, 66° W, 19 $\frac{1}{2}$ ft,

Now stump - Old Bark Blaze - No

Scribe - Blaze poor cond. - The

Creek call 5.20 chus west

Fits This location good - we

do not set Brass cap 25 Pipe is

in good cond - Make new B.T.s -

5" D. Fir N, 32° W, 16 $\frac{1}{2}$ ft.

Mkd. "45 9 CS BT"

6" Alder S, 26° E, 6 $\frac{1}{2}$ ft,

Mkd. "45 16 CS BT"

This cor. Lies on Bench in

large clear cut area now

covered with dense BRUSH &

Reprod -

June 1970

VRT.

V.D.P.

V.R. Tracy

454

C.S. File No. 54/60/50/123B