

Renewal 15/17 T323 R1W1

Found:

Brass cap firmly in ground N50,
General Land Office

45
505/519

30" D. Fir Now 32" S28 1/2 E 180

(Rec S74 E 180)

Scribe Marks visible

12" W Fir Now 16 S25 W 170

(Rec S97 W 69)

Fixed Face Not Scribed

This can set by proportion, as the
types of trees were correct,
distances good and Brass cap
firmly in ground. I put in new
bearing tree -

(Found no evidence of trees at
said bearings)

New Bearing Tree

13" D. Fir S 10 W 67 1/2

Scribed by S15 CS BT

8-5-68

~~J.M.B.~~
~~J.M.B.~~
~~M.B.~~

36

O.K. J.W.B.

C.S. File No. 5471-20

DIETZGEN NO. 385-6