

Renewal 18/17 19/20 T315 R1W

Found

12" D. Fir Now 28" Double Fir SWW 21°
opened for Scribe 19"

18" D. Fir Now 30" SSE 37°
Shows good scar

20" D. Fir Now 31" N35E 19° (Rec 17°)
Shows good scar

No trace of NW BT

(Tried to count rings of SW BT to close to count.)

Renewal

Set Brass cap at sensor MKD.

County Surveyors office

T315 R1W

518 | 517
519 | 520

1968

DIETZEN NO. 385-6

New Bearing Trees:

28" D. Fir N83W 5/2
Scribed T315 R1W 518 CS BT

4" Maple N26E 30R
Scribed T315 R1W 517 CS BT

Note:

Call on creek 53° North of
can is good.

8-26-68

J.M.D.
1968

#87

O.K. J.W.B.

C.S. File No.

54/91-102