

Renew $\frac{1}{4}$ $\frac{39}{516}$ T 315 RIW

Fd. 1923 G.L.O. BRASS CAP Bent over &

1923 B.T.S. as follows -

10" Yew S 81° W, 23 $\frac{8}{8}$ ft.

DOWN - BURNT - NO SCRIBE Fd.

8" Now 13" FIR N. 18° W, 15 $\frac{2}{2}$ ft.

Now 5N29 - shows SCRIB - we do not open.

STRAIGHTEN & RESET G.L.O. BRASS CAP AT

COR. POINT & MK. New B.T.S. -

42" D. FIR N. 65° E, 44 $\frac{0}{0}$ ft.

Mkd. " $\frac{1}{4}$ 59 CS BT "

7" Hemlock S. 5° W, 95 $\frac{0}{0}$ ft.

Mkd. " $\frac{1}{4}$ 516 CS BT "

This cor. lies 9 ft. N. of

DRY creek course S.W.

August 28, 1968

URT
F.J.
J.H.
W.P.
V.P.

V.G. Tracy

#84 O.K. J.V. 113

C.S. File No. 54/71-107