

Renew $\frac{1}{4}$ cor. $\frac{51}{512}$ T305 R2W

Fd. $1\frac{1}{4}$ " I.P. on side of, and at Base of
cedar cor. Tree, now a stump.
orig. S.E. BT. in place and
burned. Now 6' high stub. All
other BTs down and out of place
or gone. Note: Pipe Recorded
as 1" in Ren. # 34. I.P. in
good condition - we do not set
BRASS cap. MARK New BTs as
follows -

5" chingapin N. 18° E, 46 \pm ft,
scribed " $\frac{1}{4}$ 51 CS BT"

8" W. FIR S. 10° E, 80 \pm ft,
scribed " $\frac{1}{4}$ 512 CS BT"

Note: Bearings & Distances Taken
from I.P. which is 1' ft, East of
center of cedar cor. tree. This
cor. lies approx 400 ft west of
Deadman Creek Access Road on
moderate Easterly slope.

June 22, 1972

K.R.T.
L.E.M.

V. B. Tracy

#184

C.S. File No.

54/73-788
o.k. 19