

7295

Renewal R26 ^{1/4} 525 R1W

Found: BRASS CAP and 1 BEARING TREE
in excellent condition.

24" D FIR now 29" S 52° W 26 1/2 FT

shows good scar and is good for BEARING
and DIST

8" chinquapin now 9" N 28 1/2° W 35 1/2 FT

has rotten face and shows NO TRACE
of scribbing, and is good for bearing and
DIST.

NOTE: Place yellow TAGS on both BEARING
TREES

Found BRASS CAP at BEARING/DIST FROM
both BEARING TREES. (M.K.D.)

U.S. General Land office SURVEY

7295

R	1/4	R
2	525	W

19 17

New BEARING TREE

6" D. FIR N 77° W 16 1/2 FT

scribed 1/4 525 CS BT

NOTE: This 1/4 525 only lies NORTH 35 FT
FROM 1/4 530 ONLY RANGE LINE OF R1/2 W
7295 PLUS THESE CORNERS lie on STEEP
WEST Slope.

4/24/69

58
975-201
B.V. J.W.D.

F.W. J. 4/24/69
C.S. FURNER 54/82-28

DIETZEN NO. 385-6