



# THE ROBERT DOLLAR CO.

## FOREST PRODUCTS DIVISION

AREA CODE 503

TELEPHONES

OFFICE 832-5050 SALES 832-5820

GLENDALE, OREGON

June 16, 1967

HEAD OFFICE  
311 CALIFORNIA STREET  
SAN FRANCISCO 4

County Surveyor  
Douglas County Courthouse  
Roseburg, Oregon

Dear Sir:

I have found the following at the South  $\frac{1}{4}$  Corner of  
Section 32, T31S, R5W, W.M.

Brass Cap and Iron Pipe	
18" Douglas Fir S68 $\frac{1}{2}$ °E	38 LKS.
15" Douglas Fir N15° E	26 LKS.
20" Douglas Fir N57° W	34 LKS.

This corner is in good condition. No new accessories were set.

I have found the following at the North  $\frac{1}{4}$  corner of  
Section 5, T32S, R5W, W.M.

10" Douglas Fir S83°W 23 LKS. -Knocked over by logging.

12" Incense Cedar S15 $\frac{1}{2}$ °E 35 LKS. -Scribing buried under logs.

For the corner I set a 1- $\frac{1}{2}$ " x 40" Iron Pipe 32 inches into the ground and rescribed the 12" Incense Cedar  $\frac{1}{4}$ S RS 749 BT four feet above ground.

This work was done 16 June 1967, and witnessed by Sheridan Bunnell.

The Robert Dollar Co.

T. H. Mehl, III  
Registered Surveyor #749

FILED  
RECEIVED

JUN 20 1967

THM:mkb

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 55/15-4

DOUGLAS COUNTY, OREGON

Memorandum for THE ROBERT DOLLAR CO., T. H. Mehl, III

June 22, 1967

From DOUGLAS COUNTY SURVEYOR, James W. Byron

Mr. Mehl:

While posting your recent renewal of the north  $\frac{1}{2}$  corner of section 5, T32S, R5W, I note no mention of the 1962 Brass Cap as mentioned in the government field notes. The bearing trees you list as found agree with the field notes, but would like to know if you found any trace of said brass cap. Thank you in advance for this information.

Yours truly,

Lorraine R. Lewis, Deputy

*4/27/67 Telephone message - No Brass Cap Found 7/4 Corner  
Sec. 5 - T32-5*

C.S. FILE NO. 55/15-4