

30/29  
31/32

Renewal

T213 RTW

Found:

Orig BT 38" D Fir

N27E

38<sup>3</sup>

As noted no MKs. Remain:

10" D. Fir Now 12"

N35E

6<sup>6</sup>

shows good scar

16" D Fir Now 17"

S47E (Rec S53E) 19<sup>1</sup> (R. 218)

This tree has undoubtedly slid down hill.

SW & NW BT's gone.

Also 1964 BLM Brass cap out of ground.

Renewal

using orig BT & the NE BT I

Reset 1964 BLM Brass cap at cor.

which is at the top of slide-

I also set N. of cor MKD. -

over

C. S. File No. 56/25-18

DIETZGEN NO. 385-5

COUNTY SURVEYORS OFFICE

Wit. Cor. 36' W. TO

T215 R7W

S30 S29

S31 / S32

1973

New Bearing Trees for Wit. Cor -

25" D. Fir

N48E

22 1/2

Scribed T215 R7W S29 WC CS BT

8" Chiquapin

N4E

19 1/2

Scribed T215 R7W S29 WC CS BT

5-10-73

J. M. M.

D. C. C.

OK J. M. M.

#96 ✓