

2-13-74

$\frac{1}{4}$   
S10

T20S R9W  
(W $\frac{1}{4}$ )

F0

BADLY RUSTED IRON PIPE WITH  
CONCRETE CORE FIRMLY SET IN GROUND,  
BRASS CAP MISSING

FROM WHICH:

ORIG 9" NOW 18" ALDER BEARS N 80° E  
5-2 FEET, WELL HEALED AND IN GOOD  
CONDITION

ORIGINAL 8" NOW 16" ALDER BEARS  
S 22° E 25' FT., WELL HEALED  
AND IN GOOD CONDITION.

I SET BRASS CAP ALONGSIDE REMAINS  
OF ORIGINAL MONUMENT

MARKED:

COUNTY SURVEYORS OFFICE

T20S R9W

$\frac{1}{4}$   
S10

2-13-74

Larry Langley  
P.L.S.

#21 ✓

U.S. File No. 56/43-1A  
OK  
[Signature]

1974