

$\frac{1}{4}$ $\frac{3}{10}$ T305 R2W
(See Pgn. # 52)

Fr:

$\frac{3}{4}$ " I. PIPE BURIED AND DISTURBED BY
RECENT LOGGING ACTIVITY.

WE FIND AN ORIGINAL 24" FIR, NOW A
24" STUMP, PEELED, TREATED WITH PRESERVATIVE
AND COVERED WITH METAL ROOFING. WE ALSO
FIND A 30" FIR STUMP WITH AN OLD, WELL-HEALED
SCAR. THE ORIGINAL NOTES CALL FOR ONLY ONE
BT, THE ABOVE MENTIONED CAPPED STUMP, WE DO
NOT OPEN. WE ALSO FIND MARKHAM'S BEARING
TREES.

AT THE CORNER POINT WE SET A 1" X 30" I. PIPE
WITH BRASS CAP ATTACHED, MARKED;

COUNTY SURVEYOR'S OFFICE

T305

$\frac{1}{4}$ $\frac{3}{10}$
R2W

1974

#186 ✓

WE DEPOSIT THE FOUND IRON PIPE ALONGSIDE
AND NOTE THE EXISTING BEARING TREES:

AN ORIG 24" FIR, NOW A 24" STUMP BEARS
N $14\frac{1}{2}^{\circ}$ E 9 $\frac{1}{2}$ FT

A 30" FIR STUMP BEARS S 42° E 20 $\frac{0}{2}$ FT.,

A 7" NOW 11" W. FIR BEARS S 63° E 10 $\frac{1}{2}$ FT.,
(RECORD PER REN. #52 S 67° E 10 $\frac{1}{2}$ FT.)
ALIVE AND WELL-HEALED.

A 13" W. FIR NOW A 15" STUMP BEARS N 57° E
22 $\frac{0}{2}$ FT., WELL-HEALED.

A 6" W. FIR, NOW A 10" STUMP BEARS
N 21° W 8 $\frac{0}{2}$ FT., ILLEGIBLE SCRIBING
VISIBLE ON DAMAGED FACE

A 7" NOW 11" W. FIR BEARS S 21° W
15 $\frac{2}{2}$ FT., ALIVE AND WELL-HEALED.

COMPASS DECLINATION SETTING: 20° EAST

12-2-74

Larry J. Langley
PETER L. EARLE