

2-4-75

$\frac{2}{3}$
 $\frac{1}{4}$

T20S R9W

Fd:

BADLY RUSTED 1" I. PIPE WITH BRASS CAP
ATTACHED, MARKED:

U. S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$

S4 | S3

1921

FROM WHICH:

AN ORIG. 40" NOW 52" D. FIR BEARS
S35°E 23¹/₂ FT., ALIVE AND WELL-HEALED

AND AN ORIG. 40" NOW 52" D. FIR BEARS N84°W
21⁸/₈ FT., ALIVE AND WELL-HEALED.

#23 ✓

PAGE 1
C. S. File No. 5767-14 C

SE BT 52" D. FR

23 ²/₃ @ 27° .89101

21 ¹/₂

~~NW BT 52" D. FR~~

28 ³/₄ @ 39°

.77715

22 ¹/₂

1 ³/₄ @ 29° RPS

NOTE:

THE BRASS CAP AND UPPERMOST 4 INCHES OF THE ORIGINAL MONUMENT WERE INADVERTENTLY BROKEN OFF DURING THE SETTING OF A NEW MONUMENT AT THE CORNER. THE REMAINING PORTION OF THE ORIGINAL MONUMENT, A BADLY RUSTED 1" IRON PIPE FILLED WITH CONCRETE WAS PLACED ALONGSIDE THE NEW MONUMENT.

AT THE CORNER POINT WE SET A 1" X 30" IRON PIPE WITH BRASS CAP ATTACHED, MARKED:

COUNTY SURVEYOR'S OFFICE

T 20 S

S 4 | S 3
1/4

R 9 W

1975

OK [signature]

2-4-75

Mary L. Langley