

RENEWAL

1 50S R 2W  
N 1/4 S 4

SEE RENEWAL #150

FOUND


BRASS CAP LYING

6 INCHES UNDER

SURFACE IN LARGE PIT CAUSED BY  
UPROOTED TREE, CAP IS STAMPED

"COUNTY SURVEYOR'S OFFICE"

T 29 S R 2 W



T 00 S

1968

2. 32 INCH D. FIR NOW 52 INCH DIAMETER  
STUMP, BEARS S 20° E, 24 ± FEET (TO  
BLAZE). PARTIAL SCRIBING ON BLAZE.

3. 14 INCH CEDAR NOW 23 INCH DIAMETER  
BEARS S 20° W, 31 1/2 FEET, HAS  
GOOD BLAZE.

4. 6 INCH HEMLOCK NOW 8 INCH DIAMETER  
BEARS S 2° E, 19 1/2 FEET, HAS GOOD  
BLAZE.

#188 W

Q.S. FT.

67/32-43

RENEWAL

RESET BRASS CAP AT NORTH QUARTER  
CORNER SECTION 4, T30S R2W,  
MARKED AS NOTED. THIS CORNER  
LIES  $43\frac{1}{2}$  FEET EAST OF  $\frac{1}{4}$  SEC.  
33, T29S R2W (REC.  $42\frac{1}{2}$  FEET).  
SET 12 INCH DIAMETER CEDAR POST  
5 FEET LONG, 2 FEET INTO GROUND  
APPROX.  $1\frac{1}{2}$  FEET NORTH OF  
CORNER MONUMENT. THE  $\frac{1}{4}$   
CORNER FAILS IN LARGE PIT CAUSED  
BY UPROOTED FIR.

MAG. DEC.  $20^{\circ}$  E

12-18-75

L.E. MONREAN

P.L.E.

J.H.C.

OK  
*[Signature]*

Ch. No. 57/39-43