

Shaner Engineering, Inc.

PLANNING • SURVEYING • ENGINEERING
P. O. BOX 1430
ROSEBURG, OREGON 97470

FILED
RECEIVED

SEP 12 1978

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

S.E. Corner D.L.C. No. 42, T22S, R9W, W.M.

At S.E. Corner D.L.C. No. 42, T22S, R9W, W.M., I set a 2½" Brass Cap marked: "T22S, R9W, W.M., S.E. Cor. D.L.C. 42, 1977" from which Brass Cap:

40" Douglas Fir stump, badly rotted original BT, with scribes "T22S R9W 42" " visible, bears N86°W, 693.0 ft.

Original Oak BT now missing.

This Corner falls 80 ft. South of an old Quarry.

20" Douglas Fir, I scribed "T22S R9W SEC. DLC 42 BT" bears S34°E, 153.0 ft..

12 " Douglas Fir, I scribed "T22S R9W SEC DLC 42 BT" bears N69½°W, 296.7 ft..

August 10, 1977

Bruce A. Shaner, Surveyor
Mark Heimburger, Chainman

REGISTERED
PROFESSIONAL
LAND SURVEYOR

BA Shaner

OREGON
OCT. 4, 1957
BRUCE A SHANER
430