

5 | 4 T30S R2W

1/4

(SEE REN. # 57)

FD:

A 40" D. FIR STUMP, SCRIBED "1/4 S BT" ON AN UNHEALED FACE - (SEE REN. # 57)

ALL OTHER EVIDENCE OF THE ORIGINAL OR RESURVEY CORNER AND BEARING TREES HAS BEEN DESTROYED.

AT THE CORNER POINT, AS DETERMINED BY THE ABOVE MENTIONED BT STUMP, A 40" D. FIR BEARING N 69° E 88 FT.,

WE SET A 1" X 30" IRON PIPE, 24 INCHES IN THE GROUND, WITH A BRASS CAP ATTACHED, MARKED:

DOUGLAS CO. SURVEYOR

T30S R2W

1/4

55 | 54

1976

~~59/2-15~~

#195

DIETZEN NO. 3855-6

NEW SE BT 12" G FIR

S 35° E

95⁶ @ 38° .7880

75³

" 1/4 S 4 CS BT "

S 78° W 16" HEMLOCK

66° @ 23° .9205

60.7 LVL

" 1/4 S 5 CS BT "

	2.65	66
3	7.95	5.30
	6	
	19	
	15	
	15	
		60.70

	21	20
	4	94
84		
10		
94		
	20.26	35.6
		20.3
		75.3

WE MARK THE FOLLOWING BEARING
TREES:

A 12" GRAND FIR BEARS S 35° E
75 ³/₄ FT., SCRIBED "1/4 S 4 CS BT" ON A
DOUBLE BLAZE.

AND A 16" HEMLOCK BEARS S 78° W
60 ³/₄ FT., SCRIBED "1/4 S 5 CS BT"
ON A DOUBLE BLAZE.

COMPASS DECLINATION SETTING: 20° EAST

2-3-76

Gary L. Langley
PETER L. EARLE
JAMES H. COOK

OK
JHL

C. S. File No. 59/2-15