

RENEWAL

ESE  
DLC 47

T 26 SR 6 W

SEE RENEWALS NO.

50 & 140

FOUND

3/4 INCH DIAMETER

IRON PIPE IN EAST-WEST FENCE LINE.

NO BEARING TREES FOUND. THE POSI-

TION OF THIS MONUMENT FITS FOR

POSITION OF THE EAST SOUTH EAST CORNER

DLC. 47 ACCORDING TO THE COUNTY

SURVEYORS OFFICE SURVEY NUMBER

CS FILE NO C.S. 59/22

RENEWAL

AS THE BRASS CAP SET IN 1964

1.

IS NOT AT THE DLC CORNER

I REMOVE IT, AND DESTROY

SCRIBING ON BEARING TREES.

I SET BRASS CAP AT ESE

CORNER DLC 47 STAMPED

" COUNTY SURVEYORS OFFICE "

ESE  
DLC 47

T 26 S  
R 6 W

1976 C.S. File No. 59/18C

#176 ✓

DIETZGEN NO. 385-6

RENEWAL

T265 R6W  
ESE  
DLC 47

SET 3/4 INCH DIAMETER IRON PIPE  
BESIDE CAP

1 A 5 INCH DIAMETER WHITE OAK  
BEARS N 59° W, 31 FEET,  
TREE DOUBLE BLAZED AND SCRIBED  
"ESE DLC 47 CS BT".

2 A 7 INCH DIAMETER WHITE OAK  
BEARS N 16° E, 153 FEET,  
TREE DOUBLE BLAZED AND SCRIBED  
"ESE DLC 47 CS BT".

MAGNETIC DECLINATION  
20° EAST

6-17-76

L. E. MONREAN

A. V. CANQUIE

J. H. COOK

DIETZGEN NO. 385-6

G. S. File No. 59/18-2