

7295 R6W

DATE: 8-16-77

526 | 525
1/4 COR

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s 19, 143

Monument(s) Found: (Condition and Source) A 1" x 30" IRON PIPE

1 3/4 FT. SOUTH OF AN 8 INS. NOW 13 INS. DIA. MAPLE

Accessories Found: (Condition and Source) A 1 1/4 INS. NOW 2 1/4 INS. DIA.
SET BY CAIN RESURVEY, 1913 (PG. 18 FIELD BOOK #33)

FIR STUMP, UPROOTED WITH WELL HEALED BLAZE, OPENED AND

FOUND SCRIBING "526", STUMP HOLE BEARS N 89° W 38 1/2 FT.

A 30 INS. NOW 44 INS. DIA. FIR WITH WELL HEALED BLAZE BEARS

N 55° E 7 1/2 FT. A 8 INS. NOW 13 INS. DIA. MAPLE BEARS NORTH

~~1 3/4 FT.~~ A 14 INS. NOW 16 INS. DIA. W. FIR WITH WELL HEALED BLAZE

BEARS N 68° E 75 1/2 FT. A 14 INS. NOW 18 INS. DIA. DOUBLE TRUNKED

MAPLE WITH WELL HEALED BLAZE BEARS N70°E 108° FT.

A 1" IRON PIPE BEARS S35 1/2° W 10° FT., SET BY B.L.M.

8 INS. ABOVE GROUND

RENEWAL

Monument Set: (Procedure and Description) SET 1 INS. X 30 INS. IRON WITH BRASS CAP SET BY MARKHAM RENEWAL # 143

PIPE AT LOCATION OF IRON PIPE, 18 INS. ABOVE GROUND IN MOUND

OF STONE 24 INS. DIA. TO BRASS CAP MARKED

" COUNTY SURVEYORS OFFICE "

T29S R6W

S26 S25

1/4 COR
1977

New Accessories: (Description) NONE

Location and Comments:

20° E

Compass Declination

DCSO

Agency

R.B. KIMBERLING

Party Chief

R.B. Kimberling

Notekeeper

M.W. CLINE

Witnesses

OK
[Signature]