

DATE: 12-8-77

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

5  
6  
2  
0  
T315 RIW  
$$\begin{array}{r} 515 \\ \hline 522 \end{array} \begin{array}{l} C \\ C \end{array}$$

1923

Previous Renewal #'s 96

Monument(s) Found: (Condition and Source) 2 1/2" BRASS

CAP STAMPED AS SHOWN. PIPE IS  
LOOSE IN GROUND & LEANING BADLY.

Accessories Found: (Condition and Source) 3/4" IRON ROD

IN TOP OF ORIGINAL <sup>3/4"</sup>B. T. STUMP BEARS  
N 35° E, 22.7' STUMP HAS WELL HEALED  
SCAR.

3/4" IRON ROD IN TOP OF ORIGINAL  
3/8" B. T. STUMP BEARS S 55° E, 4.1'  
STUMP HAS A WELL HEALED SCAR

#1634

RENEWAL

Monument Set: (Procedure and Description) USING THE  
3/4" IRON RODS SET BY POWELL FOR  
REFERENCE, I RE-SET THE BRASS CAP  
& PLACED A MOUND OF STONE  
AROUND THE MONUMENT.

New Accessories: (Description) NONE AVAILABLE.

Location and Comments:

U.S.F.S. Compass Declination  
Agency  
DENNIS GAYLORD Party Chief  
" " Notekeeper  
ROLAND SIMSHAUSER Witnesses

*OK gh*