

T 20-11

15/14
22/23

DATE: 19 May 1978

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s CS 53/66 #53

Monument(s) Found: (Condition and Source) 2" BRASS CAP ON
a 1" pipe; firmly set. MKD county
Surveyors Office 1968

515	514
522	523

Accessories Found: (Condition and Source) FD. 35" D-Fix
stump, Bys. N85°E, Dist. 13⁴⁸ scribing visible
"1W", ORIGINAL bearing Tree. FD. 45" D-Fix
stump, Bys N39W, Dist. 9⁸ ORIGINAL
bearing Tree. FD. 60" D-Fix stump, bvs.
N11°E, Dist. 46⁹⁴ scribing visible;
T20S R11W, S14 CSBT.

#117x

RENEWAL

Monument Set: (Procedure and Description) Reseted County
BRASS CAP; N 41° 30' E, DIST. 155'; To
GLO CALL'S distance to original Bearing
Tree. I have previous discuss the resetting
of the county cap with our county surveyor Francis
L. INGRAM.

New Accessories: (Description) New BEARING AND DIST.
45" D-Fir stump brs. N 45 1/2 W, Dist. 9¹⁴
35" D-Fir stump brs. N 88 1/2 E, Dist. 12⁵⁴
60" D-Fir stump brs. N 9° E, Dist. 45⁶⁸
Bearing are to visible scribing; and DISTANCE
are to the center of tree at its root crown.

Location and Comments:	<u>20° E</u>	Compass Declination
Go on USFS ROAD	<u>County Surveyor office</u>	Agency
1908 (new 4811) 0.7	<u>Ernesto R. ALVARADO</u>	Party Chief
mile from Road	<u>" "</u>	Notekeeper
Junction 2059 To	<u>Colin Long</u>	Witnesses
Location Poster on		
Right side of the		
Road. The TAKE old		
spur to the Landing.		
The corner lies approx. 250 feet		
due north of the Landing.		

OK 