

Government corners re-established.

1/4 section corner between sections 4 & 5

Tp.23 S.R.4 W!

One old bearing tree gone, the other standing but decayed and old marks almost obliterated. *set cedar post 3x4x36"*

marked a fir 20 inches in diameter which bears North 82 degrees West 45 lks. distant and marked 1/4 S.B.T. C.S.

a fir 22 inches in diameter which bears North 45 degrees East 21 lks. distant and marked 1/4 S.B.T.C.S.

Witness George Williams
Luther Daugherty.

1/4 section corner between sections 34 & 35

Tp.22 S.R.4 W.

Original bearing trees fallen. The S.E. tree a large Cedar (Redwood) being down a number of years but there was sufficient evidence it was the original bearing tree. I was at the corner in 1911 the tree was standing.

Set ~~sawed~~ fir post 4 x 4 inches 3 ft. long and drove an iron pipe 2" in diam. 2" " along side.

marked a fir 26 inches in diameter which bears North 40 degrees West 14.7 ft. distant and marked 1/4 S.B.T. C.S.

a fir 24 inches in diameter which bears North 70 degrees East 34.5 ft distant and marked 1/4 S.B.T, C.S.

Witness
E.W. Kissling
Dan. Wright.

Con #18

*Phill
Nov 1944*

Hull & Bradford June 6th 19~~05~~⁰⁴

Begin at the $\frac{1}{4}$ cor. bet. sec 11 & 14 Tp. 238 R. 4
N. South from corner.

5.00 top desc to creek. 17.35 cr. C. N. ave.

20.00 set a cedar post on steep North slope
no bearing trees bal. dist. 4.00

C.N. 1/16
S. 14
NOT RECORDED

May 7th 30

Cayberd

South from $\frac{1}{4}$ cor 6.60 cr. C.N.E. 20.24

Cedar post marked cedar 6.875" N 19 fur 6.815 2.25

S 89 1/2 W 20.00 dogwood post marked

fir 40" 8 1/2 N 46 1/2 fur 20" N 11 E 46

From cor of fence N. 41.15 to rock

which
1/16 ?

D.F.
THEIL

C.S. File No.

61/5-5
~~52/393~~