

~~should have been a RENEWAL - 2/28/84 Bill~~

DATE: 1/10/80

T 235 R 7W

S 20	S 21
S 29	S 28

- Condition Report On
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 45 and BLM dependent resurvey of
subdivisional lines T 235, R 7W 1963

Monument(s) Found: (Condition and Source) _____

2 1/2" iron pipe with brass cap marked T 235 R 7W
monument is firmly set and
protrudes 6" from ground.

S 20	S 21
S 29	S 28
1963	


Accessories Found: (Condition and Source) A double trunk

maple east trunk 28" DBH west trunk 33" DBH, bears
N. 85° E., 123 1/4 ft as per BLM resurvey, west trunk has
double blaze, upper blaze fully healed, lower blaze is par-
tially healed with some illegible scribing visible.

An 18" now 20" white oak, bears S. 88° E., 71 1/2 ft as
per renewal # 45, double blaze no scribe marks visible
(updated in BLM resurvey)

Ren# 163

6/16-1



should have been a Renewal (2/28/84) ^{Typed} BS

A 15" now 20" white oak, bears $S. 65 \frac{1}{2}^{\circ} W.$, $124 \pm$ ft (record)
 $S. 65 \frac{1}{2}^{\circ} W.$ (58 ft)
 as per BLM resurvey, single fully healed blaze. (did not open)

A 16" now 20" white oak (southerly one of two closely growing trees), bears $N. 11 \frac{1}{2}^{\circ} W.$, $10 \pm$ ft as per renewal #45, fully healed double blaze.
 (Updated in BLM resurvey) RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) All bearing trees mentioned above tagged with standard DCSO bearing tree tags. Tags are marked with record bearings and distances as noted above.

Location and Comments:	<u>19° E</u>	Compass Declination
	<u>DCSO</u>	Agency
Rep. <u>Stephen John Thomas</u>	<u>AGZ</u>	Party Chief
	<u>D Aderbury</u>	Notekeeper
	<u>D S Prado</u>	Witnesses
	<u>K Mosley</u>	

OK *[Signature]*