

DATE: 2/28/80

T295 R5W

$\frac{1}{4}$ $\frac{S11}{S14}$

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #26, #114

Monument(s) Found: (Condition and Source) DCSO Brass cap
on 1" x 30" LP marked T295 R5W firmly set but
 $\frac{1}{4}$ $\frac{S11}{S14}$ not plumb pro-
1961 trading approx
14" from ground

Accessories Found: (Condition and Source) Original 16" now
37" B.oak S 30°W, 113[±] ft. (record S 30°W, 116[±] ft),
shows good scars, center rotted, no scribing visible.
No evidence of other original BT.
From renewal #26 a 10" now 27" maple N45°E,
82[±] ft. (record N45°E, 84[±] ft.) section of trunk
with upper blaze unhealed and scribed $\frac{1}{4}$ S11 CS
has fallen off tree, lower blaze still intact on standing
tree partially healed with BT visible.

#205 ~~X~~

From renewal #114 a 19" now a 12" W. oak, S 09°W
33[±] ft. (record S 10°W, 33[±] ft.) well healed double
blaze, no scribing visible

RENEWAL
Because position of Found Brass cap does not agree with original Monument Set: (Procedure and Description) we reference
out 1961 brass cap remove and replace with
5/8" I.R. and unmarked DCSO aluminum cap.

We set 1961 brass cap at record bearing and
distance from original 16" B. oak BT and add
stamping "RESET 1980" Cap now protrudes 0[±] ft.
from a mound of stone measuring 14" x 20" x 10" high.
New Accessories: (Description) Here recorded are new

bearings and distances to existing trees, original
16" B Oak S 30°W, 116[±] ft. A 27" Maple N 45¹/₂°E, 79[±] ft.
A 12" W. oak S 10°W, 36[±] ft. Also we ^{double} blaze and scribe
1/4 S 11 CSBT on a 6" B. oak N 28°W, 24[±] ft.

A 5/8" Iron rod (prop corner of Longhorn ranches subd.)
bear S 87°E, 70[±] ft. The 5/8" Iron rod marking position
Location and Comments: 19° Compass Declination
of 1961 Brass DCSO Agency
Cap bears S 30°W Deputy Stephen J. Blaise Party Chief
SHAWN MEANS Notekeeper
3[±] ft. SHAWN MEANS Witnesses

OK [Signature]