

DATE: 3/10/80

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1952 BLM RE-SURVEY

Monument(s) Found: (Condition and Source) T20S R10W Sec. 4&5, 1/4
1/4 Cor.)
U.S.G.L.O.S. brass cap on 1" iron pipe, mkd.: S5 S4
1952

Iron cap on 1 1/2" iron pipe adjacent to brass cap, mkd.: 1/4 S4
1/4 S5

Accessories Found: (Condition and Source) _____

30" D-Fir, brs. N57°E, dist. 32⁸', healed face (N58°45'E 33.66)

46" D-Fir stump, approx. 3 1/2' high, brs. N76°45'W, dist. 19³' (N75°W 19.14)

lower part of healed blaze remains.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Attention and boundary signs on metal fence posts placed
East and South of corner.

Location and Comments:

Take Burma Rd. to I.P. 20°E
Rd. #20-10-4.1 to Deputy Co. Surveyor
landing at end. Brushed Ernest R. Abramo
line is approx. 40' North Carol Dickison
of landing. Follow line Colin Long
West approx. 1400' (horiz.)
to 1/4 cor., which lies on South slope.
approx. 35' above branch.

Compass Declination
Agency USFS
Party Chief
Notekeeper
Witnesses

OK ghl