

DATE: 3/14/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s M69-78

Monument(s) Found: (Condition and Source) (T20S R10W, Sec. 4,

Cl/16 S-4-80)

5/8" re-bar, approx. 3" above ground

(SW cor Lot 2)  
Gout

Accessories Found: (Condition and Source) \_\_\_\_\_

(26") 30" Hemlock, brs. N77°E, dist. 14<sup>18</sup>/<sub>100</sub>' , open face, scribing

visible: Lot 2 BT, (N76°30'E 14.1)

(29") 35" D-Fir, brs. N4°E, dist. 22<sup>43</sup>/<sub>100</sub>' , open face, scribing

visible. (N5°30'E 22.4')

X

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

USFS Attention signs and boundary signs on metal

fence posts placed South and East of corner.

Location and Comments:

Take Burma Rd. to I.P.  
Rd. #20-10-3.0. From  
location poster at  
landing at end of rd.,  
corner lies N20°W,  
dist. 374' on flat area.

(Location poster is at junction w/ proposed  
USFS Rd. #2319-034.)

20° East

Deputy Co. Surveyor

Ernest R. Alvares

Carol Dickison

Colin Long

Compass Declination

Agency USFS

Party Chief

Notekeeper

Witnesses

*OK JHL*