

DATE: 3/18/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #22 T19-10

Monument(s) Found: (Condition and Source)

	T19S	R10W
U.S.G.L.O.S. brass cap in good condition, mkd.:	33	34
	4	3
	T20S	
	1952	

Accessories Found: (Condition and Source)

- 18" D-Fir, brs. N52°E, dist. 641', healed blaze
- 13" D-Fir, brs. N30°W, dist. 1090', healed blaze
- 13" Fir snag, approx. 35' high, brs. S23°W, dist. 686', healed blaze
- 12" D-Fir, brs. S54°30'E, dist. 1378', healed blaze.

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

Attention and Boundary signs on metal fence posts placed

South and East of corner.

Location and Comments:

Take Burma Rd. to I.P. Rd. #20-10-3.0. Location poster is on North bank above entry to landing approx. 300', on flat area below landing. Landing is approx. 0.3 miles from junction w/ 20-10-3.1.

20°E

Deputy Co. Surveyor

Ernest R. Alvarado

Carol Dickison

Colin Long

Compass Declination

Agency USFS

Party Chief

Notekeeper

Witnesses

*OK [Signature]*