

DATE: 3/19/80

West WC for 1/4 T19S
514
523
R9W

Condition Report Only:
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1958 Resurvey

Monument(s) Found: (Condition and Source) A BLM Brass Cap
on a 2 inch iron pipe firmly set and protruding
0.5 feet from ground. Cap is marked
US Cadastral Survey

T19S R9W

WP

S 14
523

1958

Bureau of Land Management

Accessories Found: (Condition and Source) From 1958 resurvey
an 11 inch hemlock now a 12 inch by 2.5 feet
tall rotted stump Bears S 42 3/4° W, 2.6 feet
blazes are rotted but scribed BT is visible
has a US Plywood BT tag marked as
per record. North West BT from resurvey
is missing. We also find two unrecorded

C. S. File No. 61/6-11

Sheet Page 1 of 1

BT's. A 17 inch Hemlock ^{bears} $AS 45\frac{1}{2}^{\circ}W, 53^{\circ}ft$

(US Plywood BT tag reads reverse bearing, and distance $N 49^{\circ}E, 53^{\circ}ft$.) scribed WC T 19 S R 9 W S 23 on a single unhealed blaze marked with yellow paint.

RENEWAL

Accessories Cont'd.

Monument Set: (~~Procedure and Description~~) A 17" Hemlock bears $S 74^{\circ}W, 39^{\circ}ft$ (US Plywood BT tag reads reverse bearing and distance $N 76^{\circ}E, 39^{\circ}ft$) scribed WC T 19 S R 9 W S 23 on a single un healed blaze marked with yellow paint.

New Accessories: (Description) Because of unrec
orded nature of BT's we do not
retag but leave as found. No other
trees available.

Location and Comments: 19°E Compass Declination
RCSO Agency
Deputy Stephen J. Flouse Party Chief
Stephen J. Flouse Notekeeper
SHAWN Means Witnesses
Nathan Reed

OK
