

DATE: APRIL 16, 1990

T235 RTW

DLC
#38

S 33

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s # 135A

Monument(s) Found: (Condition and Source) GARRETT'S 12" x 12"

sandstone from renewal 135A which when ref-
erenced out and removed from ground we
find to measure 14" x 14" x 16". Sandstone is marked
with "X". Sandstone is at corner of fences running

East, West and South 

Accessories Found: (Condition and Source) Search for but find

no evidence of original 18" oak BT. From renewal
135 A a 28" now 30" PBH D. Fir bears N45°E, 7⁰ ft
(as per record) has partially healed double blaze with
scribed "D" visible.

#154 X

RENEWAL

Monument Set: (Procedure and Description) We perpetuate
position of corner at sandstone as accepted by Garrett.
We reference out sandstone and remove replacing
it with a standard DCSO Brass cap ^(on 1"x30 iron pipe) marked "DOUGLAS COUNTY SURVEYOR"
(cap is) T23S RTW
We place sandstone on south edge of DLC ┌
cap. Both cap and stone are firmly set 38
and protrude 0+ ft from ground. 1980

New Accessories: (Description) A 12" B. oak bears N87°E
67° ft., scribed "NW DLC 38 CS BT" on a double blaze.
A 24" B. oak bears S02°W, 109² ft., scribed "NW
DLC 38 CS BT" on a double blaze. We tag trees with
DCSO BT tags.

Location and Comments: 19°E Compass Declination
DCSO Agency
Deputy Stephen Flouse Party Chief
Stephen Flouse Notekeeper
TERRIE PLOUFF Witnesses
SAAWN MEANS

OK *[Signature]*