

DATE: 5/12/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 8, 72

Monument(s) Found: (Condition and Source) \_\_\_\_\_

County brass cap in good condition, mkd.: T20S R11W

S26

2" iron pipe alongside cap

1/4

S35

1968

Accessories Found: (Condition and Source) \_\_\_\_\_

Go to ... place ... to lower barn.

16" Maple, brs. N64°E, dist. 78.3'

11" Maple, brs. S39°W, dist. 93.0'

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

Attention sign on metal fence post placed near corner

B.T.'s painted with red blazes and 6" bands

Area flagged with pink "Land Line" ribbon

Note: All distances are to side and center of trees at root crown.

Location and Comments:

20° E

Compass Declination

Go to Mr. S. Black's farm, then to larger barn. From a location poster just North of the barn, go West approx. 965', crossing both creeks.

Douglas Co. Dep. Surveyor

Agency USFS

Ernesto R. Alvarado  
(same)

Party Chief  
Notekeeper

Colin Long, Survey Tech.

Witnesses

The corner is 18.6' East of the second creek, between the creek and the cat road.

OK  
*[Signature]*