

DATE: July 7, 1980

T305 R1E

1/4 529
532

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s None

Monument(s) Found: (Condition and Source) An iron post 1" in diam.
and 3 ft. long with a 2 1/2" brass cap protrudes 17"
from ground. Monument is slightly loose and leaning southwest.
Cap is marked

" U.S. GENERAL LAND OFFICE SURVEY "

1/4 529
532

1923

Accessories Found: (Condition and Source) Original 12" Cedar
now a 13" Cedar bears N48 1/2° E, 9± ft. dist. (record
N51° E, 9± ft. dist). This tree has a partially healed
single blaze with "4 S 29 B" visible.

An original 38" now a 40" D. fir bears S 28 1/2° W,
24± ft. dist. (record S27° W 24± ft. dist.) This tree
has a well healed single blaze with no scribing visible.

#45 ✓

G.S. File No. 61/11-6

RENEWAL

Monument Set: (Procedure and Description) Because monument may be disturbed by road construction it is not reset but 2 new bearing trees which will be safe from planned road construction are marked.

New Accessories: (Description) A 16" Madrone bearing N 32° E, 46⁶ ft dist. is bark scribed "1/4 S 29 CS BT".
An 18" W. Fir (with a leaning curved trunk) bearing N 48° W, 43⁸ ft. dist. is scribed "1/4 S 29 CS BT" on a double blaze. Both trees are tagged with DCSO BT tags. No other suitable trees available until road construction is complete.

Location and Comments: 19° E Compass Declination
DCSO Agency
Deputy Stephen Jon Fause Party Chief
Stephen Jon Fause Notekeeper
E. Rueben Scott Witnesses

[Handwritten signature]

$\frac{1}{4} \quad \frac{29}{32}$

T30S, R1E

Reference cut

(B.T. to south
will be destroyed
in road construction)

Top of road cut
will be about 15'
south of monument,
clearing limits about
10' south of monument

C. S. File No. 6111-6