

FILED  
RECEIVED

GOVERNMENT CORNER RESTORATION FORM

Township 26 Range 5W Sec. 30 County DOUGLAS MAY 24 1984

State OREGON Date MAY 21, 1984 No. \_\_\_\_\_ COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

T265  
R6W 1/4 R5W  
S25 | S30

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 18, 24, 150

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

FROM RENEWAL #18: A 3/4 INCH IRON ROD FIRMLY SET AND PROTRUDING APPROXIMATELY 1 INCH FROM GROUND, EDGE OF SANDSTONE MONUMENT VISIBLE ON NORTHEAST SIDE OF IRON ROD (DID NOT UNCOVER)

THIS MONUMENT WAS NOTED AS NOT FOUND IN SURVEY M96-52.

Accessories Found: (DISTANCES NOT MEASURED)

ORIGINAL W. OAK, S64 1/4° E, IN GOOD CONDITION. (RECORD DIST. 791.2 FT)

FROM RENEWAL #24 A W. OAK, S66 1/2° E, DEAD BUT SOUND AND STANDING. (RECORD DIST. 483.5 FT)

FROM RENEWAL #150 TWO PROPERTY CORNER MONUMENTS IN SADDLE BUTTE ESTATES, 1ST ADDITION: THE NORTHWEST CORNER OF LOT 15, N13 1/4° E, A 5/8 INCH IRON ROD PROTRUDES 10 INCHES FROM THE GROUND AND IS BENT OVER TO THE SOUTHEAST. (RECORD DIST. 423.7 FT)

THE SOUTHWEST CORNER OF LOT 16, N56 3/4° E A 5/8" IRON ROD FIRMLY SET AND PROTRUDING 4 INCHES FROM THE GROUND. ALUMINUM CAP MARKED "SHANER ENGINEERING" IS MISSING. 6 INCH SQUARE X 6 FOOT TALL CEDAR POST NORTH OF IRON ROD IS MISSING. (RECORD DIST. 314.1 FT)

