

GOVERNMENT CORNER RESTORATION FORM

Township 20 S Range 11 W Sec. 19 County DOUGLAS
State OR Date 6/10/92 No. _____

Corner Designation

S25 | S19

S30

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals # 20 (T20-12) (# 25 T20-11)

Monument(s) Found: (Condition and Source)

3" DIA. BRASS CAP ON A 1/4" O.D. IRON PIPE, PROTRUDING 12" ABOVE GROUND. (REN 20)

MONUMENT DETAIL

T20

R 12 | CC S25 | S19

S30 | R 11

399

Accessories Found:

18" NOW 24" DIA. UPROOTED AND DOWN ROTTING SPRUCE, TRUNK IS EARTH COVERED, ROOT HOLE BEARS N 44° E, 21.8 FT (AGREES WITH REC) ORIG. BT.

20" NOW 30" DIA. UPROOTED AND DOWN ROTTING HEMLOCK, TRUNK UNEARTHED, A BLAZE WITH ILLEGIBLE SCRIBE MARKS FOUND, ROOT HOLE BEARS S 80° W, 14.5 FT (AGREES WITH REC) ORIG. BT

8" DIA. HEMLOCK NOW ROOTS FOUND, BEARS S 66 1/2° E 21.1 FT ORIG. BT?

4" NOW 21" DIA. HEMLOCK WITH A FULLY HEALED SINGLE BLAZE FACING N 30° W, BEARS S 78° E, 10.7 FT (AGREES WITH REC) REN # 20

4" NOW 12" DIA. R. CEDAR WITH A FULLY HEALED SINGLE BLAZE, BEARS S 4° W, 7.1 FT (REC. S 4° W, 7.8 FT) REN # 20

#215 T20-11 X
#120 T20-12 X

G.S. File No. 107/26-70

