

GOVERNMENT CORNER RESTORATION FORM

FILED

jh

Township 275 Range 5W Sec. 28 County DOUGLAS

MAY 12 1993

State OR Date 4-28-93 No. _____

Corner Designation

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

$\frac{1}{4} \frac{S28}{S33}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1963 BYRON

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DCSO BRASS CAP ON A 1 1/2" O.D.
IRON PIPE PROTRUDING 12" ABOVE
GROUND (1963 BYRON)

COUNTY SURVEYORS OFFICE
T 275
 $\frac{1}{4} \frac{S28}{S33}$
RSW
1963

Accessories Found:

12" NOW 22" DIA B.OAK WITH A PREVIOUSLY OPENED
BLAZE, NO SCRIBING VISIBLE, BEARS S33°E, 9.2 FT
(AGREES WITH 1963 BYRON REN) ORIG. BT

12" NOW 25" DIA B.OAK WITH A PREVIOUSLY OPENED
BLAZE, NO SCRIBING VISIBLE, BEARS N 13°W, 9.2 FT
(AGREES WITH ORIG REC, REC RECORDING ERROR IN 1963 BYRON REN)
ORIG. BT

12" NOW 16" DIA. B.OAK WITH A FULLY HEALED
DOUBLE BLAZE, BEARS N76 1/2°W, 40.8 FT (REC. N75°W, 41.5)
1963 BYRON

14" NOW 16" DIA. D.FIR WITH A FULLY HEALED
DOUBLE BLAZE BEARS S68°W, 39.5 FT
(AGREES WITH REC) 1963 BYRON

