

Date: 8/24/2012 By: JC

This survey consists of:

Map: This corner report was downloaded  
from the Jackson Co. Surveyor's

Narrative: Office web site 8/24/2012

Corner Rpt: CS 65/77-23

SECOND RE-ESTABLISHMENT  
GCDB 400700DOUGLAS COUNTY  
SURVEYORSection corner common to Section 33 of Township 30 South and Sections 3 and 4 of Township 31 South,  
Range 2 East, W.M.Found at corner position, exposed 10 ins., the 2 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap  
set by L. Carter of the GLO in 1937 and marked:

T30SR2E  
S33  
—  
S4 | S3  
T31SR2E  
1937

Original bearing trees recorded by Peter Applegate of the GLO in 1891 found with healed blazes and  
measured to center at base;

S. fir rotted snag brs. record S 7° E, 29.0 ft.

S. fir snag brs. record S 41° W, 53.5 ft.

1937 GLO brass cap for Sections 33 and 34 of Township 30 South Range 2 East  
brs. record S 87½° E, 82.7 ft.Bearing tree recorded on first re-establishment in 1978 found with healed double blazes and measured  
to center at lower blaze;

W. fir snag brs. record N 26¾° W, 38.4 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

Cedar 6 ins. diam. brs. S 31¾° E, 7.4 ft.

Cedar 8 ins. diam. brs. S 42° W, 16.2 ft.

Corner lies approx. 300ft. east of old faint road to survey shelter.

July 15, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P – 148

V – 16°30'