

CORNER REPORT FORM

FILED

Section 33
Douglas County
PLSS Number

300100

Township 32S Range 7W
Date 9-2014

Date: 9-17-2014 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/86-19
DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

SC 32/33 only

- Condition report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

PRICE 1954 CS 41/301
TEMPLIN 1995 M 122-53
DCSO - CS 64/64-7

Monument(s) & Accessories Found: (Condition and Source)

2" O.D. IRON PIPE
18" D. FIR STUMP N41 1/2 E 30.4 FT
16" D. FIR N10W 27.8 FT HEALED SCAR
5" T. OAK S89E 5.2 FT
6" CHINGHAPIN S50W 25.7 FT

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Surveyor's Seal

Location & Comments

AREA BADLY
burnt 2013
CORNER ON
North slope
Approx 50' South
OF ROAD

Compass Declination 15 1/2
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470
Party Chief: N. Frountal
Notes:
Witness: D. MAURING

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QIMBY
1054

EXP 12-31-14

C.S. File 65/86-19