

FILED

Date: 9-30-2015 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C565/89-28

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 14 Township 31S Range 3W

Douglas County Date 9/2015

PLSS Number 600400

CORNER DESIGNATION

See COR 514/513
523/524

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Markham 1969 C/S 42/392

Monument(s) & Accessories Found: (Condition and Source)

- FD 1/2" Iron Pipe
- 30" FIR N70E 18.3 FT (Rec N65E 18.5 FT) GOOD SCAR
- 27" FIR S55E 11.9 FT (Rec S58E 12.5 FT) VIS SCRIBES
- 36" FIR S31W 37.0 FT GOOD SCAR
- 20" WINDPONE N62W 25.2 FT (REC N67W 24.4) GOOD SCAR

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

PLACED 60D spike in base @ side center of tree's

Location & Comments

AREA BADLY
BURNED 8/2015

Compass Declination 15 1/2° E

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. Fromdahl

Notes:

Witness: R. OLSON

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-16

C.S. File 65/89-28