

FILED FEB 23 2000

T283 R4W ^{Y454} S3 2-15-00

14" NOU 20" DIA 4 1/2 FT

HIGH D. FIR STUMP WITH VISIBLE
SCRIBING "1/5" BEARS N 90° W
9.2 FT OBT

13" NOW DOWN AND ROTTED CEDAR
WITH VISIBLE SCRIBING "Y454BT"
BEARS N 71° W, 32.3 FT 1957

1957 BLM BRASS CAP IRON PIPE

RM FOUND OUT OF GROUND NO
POSITION

ORIG. CORNER TREE NOW ROTTED
ROOTS CORNER LIES AT FENCE
CORNER WITH FENCE LINES RUNNING
N - S + W.

NEW

6" DIA D. FIR DOUBLE BLAZED AND
SCRIBED "Y453 CS BT" BEARS
558° E, 25.8 FT

10" DIA I CEDAR DOUBLE BLAZED AND
SCRIBED "Y453 CS BT" BEARS
N 31° E, 40.3 FT

11" DIA I CEDAR DOUBLE BLAZED AND
SCRIBED "Y454 CS BT" BEARS
N 54 1/2° W, 70.2 FT

ON BACK

C.S. File No. 66/14-23

6" DIA O. FIR DOUBLE BLAZED
AND SCRIBED "Y4S4 CS RT"
BEARS S 53 1/2° W 69.3 FT

1958 BLM BC/IP RM MISSOURI

31" LONG I.P. IS 2 1/2" O.P.

GLASS CAP HAS A DIA OF

3 1/4" WE USE THIS MONUMENT

TO REESTABLISH CORNER

STAMPING OUT RMR AND

ADDING "S4 DC SO RESET 2000"

U.S. CADASTRAL SURVEY

T 28 S R 4 W

DC SO

1/4 S4/S3

RESET

1958

2000

BUREAU OF LAND MANAGEMENT

PROTRUDE 5" ABOVE GROUND

N 1/4 S4/S3 FP OK

2-16-00

CS 66/14-23