

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: 9/26/2007 By: JC

This survey consists of:

Township 24S Range 5W Sec. 23

County DOUGLAS

State OREGON Date AUG. 27, 2007

No. 600340

Narrative: Corner Rpt: 67/24-14

Corner Designation

1/4  
S23/S24

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals BYRON 1960, SWEDEN 1998 (COND. REP.)

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 2 1/2 INCH DIAM. BRASS CAP MARKED AS AT RIGHT ON A 1 INCH DIAM. IRON PIPE FIRMLY SET AND PROTRUDING APPROX 14 INCHES ABOVE GROUND IN A NORTH-SOUTH RUNNING FENCE LINE. MONUMENT IS APPROX 150 FT. SOUTH FROM AN EASTERLY-WESTERLY RUNNING FENCE LINE. (1960 RENEWAL)



Accessories Found:

NO ORIGINAL BTs FOUND. ANY REMNANT OF NW BT AS FOUND IN 1960 IS NOT LOOKED FOR; LOCATION FALLS IN VERY LARGE BRAMBLE PATCH.

ONE 1960 RENEWAL TREE FOUND. NE BT NOT FOUND IN 1998 WAS REMOVED WHEN FIRE-TRAIL WAS BUILT ON EAST SIDE OF FENCE. THE 11" W. OAK NOW A 14 INCH DB.H. WHITE OAK WITH A FULLY HEALED DOUBLE BLAZE THE BASE OF WHICH BEARS N 72° W, 48° FEET DISTANT (RECORD N 68° W, 49° FT.); THIS IS NOW A DOUBLE TRUNK TREE WITH A SMALLER SOUTHERLY TRUNK. THE CENTER OF THE ROOT CROWN OF THIS DOUBLE TRUNK TREE BEARS N 72° 1/4° W, 47 L FT. DISTANT.

C.S. File #: 67/24-14

