

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: 7/31/2012 No. X
This survey consists of:

Township 30S Range 06W Sec. 4

County DOUGLAS

State OREGON

Date JULY 20, 2012

No. 340600

Corner File: CS 67/36-19

Corner Designation

$\frac{1}{4}$ $\frac{S4}{S9}$

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1951, 1967

Monument(s) Found: (Condition and Source)

FROM 1967 BLM RENEWAL:
A 3 1/4 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 2 1/2 INCH O.D. IRON PIPE, FIRMLY SET AND PROTRUDING 9 INCHES ABOVE GROUND.

Accessories Found:

FROM THE 1951 RENEWAL A 1 INCH I.D. IRON PIPE (DETERMINED TO BE ERRONEOUS 1/4 CORNER MONUMENT BY 1967 B.L.M. RESURVEY) IS FIRMLY SET, PROTRUDING 6 INCHES ABOVE GROUND; BEARS N68°E, 24 1/2 FEET DISTANT (AGREES WELL WITH RECORD N68°E, 0.375 CHAINS)
ALSO FROM 1951 A 15" FIR NOW AN 18 INCH DIAMETER 6 FOOT TALL SAWN FIR STUMP WHICH IS NOW VERY ROTTED AND SHOWS NO CLEAR BLAZES OR SCRIBING; BEARS N26°E, 48° FEET DISTANT (AGREES WITH TIE COMPUTED FROM B.L.M. RECORD).

EVIDENCE OF ONE ORIGINAL BEARING TREE (AS DETERMINED BY B.L.M.) A RED FIR 3" DIAM. NOW A 38 INCH DIAMETER DOUGLAS FIR WITH A PREVIOUSLY OPENED SINGLE BLAZE SCRIBED "1/4 S BT" (BLAZE SURFACE IS TWISTED AND FACES APPROX. N35°E); BEARS S80°E, 31 1/2 FEET DISTANT (AS PER RECORD). BAD BLAZE FACE DIRECTION MAY BE DUE TO VERY SMALL ORIGINAL DIAM. WE CHECK THOROUGHLY FOR EVIDENCE OF ANOTHER O.B.T. BUT FIND NONE.

EVIDENCE OF THE ONE 1967 NEW BEARING TREE:
A FIR 8" DIA. NOW A 17 INCH DIAMETER DOUGLAS FIR WITH A FULLY HEALED, LOW, SMALL, SINGLE BLAZE; BEARS N38 3/4°E, 48 1/2 FEET DISTANT (AS PER RECORD).

C.S. File No 67/36-19

U.S. DEPT. OF AGRICULTURE

T 30S R 6W

$\frac{1}{4}$ $\frac{S4}{S9}$

1967

CADASTRAL SURVEY

BUR. OF LAND MANAGEMENT

