

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 30 PLSS # 100200

Date: 11/24/2021 By: X

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 5-19-21

Map: _____

Narrative: _____

Corner Rpt: 67/51-5

DOUGLAS COUNTY SURVEYOR

Corner Designation

SEC COR 25/30
36 31
R3W R2W

- Condition Report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals DCSD 1966
Monument(s) Found: (Condition and Source)

MONUMENT DETAIL

2 1/2" BRASS CAP ON 1" IRON
pipe projects 12" above
ground

County Surveyors
OFFICE
T26S

BLM Resurvey 1981 Vol 45
Pg. 17436-37

R	525	530
3	536	531
W		

Geisler Champion International
1989 CS 43/60-5
DCSD 2020 CS 67/46-39
Accessories Found

1966

1913 BEARING Tree 36" D. Fir S45°E 21^{ft}
Chopped FACE visible Scribe

9" D. Fir S37°W 7^{ft} GOOD SCAR

9" D. Fir N5°W 16^{ft} GOOD SCAR

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

10" FIR N77°E 37.7 FT PARTLY HEALED DOUBLE
BLAZE (unfiled BLM survey)

Lat 43° 27' 30.9937" N
122° 09' 07.1637" W

Sketch of Monument, Accessories, and General Area

Location & Comments

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. F. AUSE
Note keeper _____
Witnesses J. LORSUNG.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 14, 1978
RONALD A. QUIMBY
1854

Expires: 12/31/2022

BURN REVISIT 5/19/21

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; 25 & 36, T26-3

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ronald Geisler, for Champion International (Lynn Sibley; Dean Turner, field crew) June 30, 1987 - C.S. File 63/60-5

Found - 1966 County 2 1/2" brass cap on a 1" iron pipe extends 12" above ground.

9" D.Fir bears S.37°W., 7.5 ft. healed face.

9" D.Fir bears N.5°W., 16.4 ft. healed face.

36" D.Fir bears N.45°W., 21.8 ft. chopped face. bearing marks visible. (Orig. BT)

8" D.Fir now down & uprooted bears N.61°E., 4.5 ft.

New BT - 5" D.Fir bears N.74°E., 23.3 ft. scribed "T26S R2W S30 BT".

Now BURNT, BLZ VIS

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 9/2/2020 - C.S. File 67/46-39

Found ok

(1987) 36" D.Fir quad error (see 1913 GLO record) should be S.45°E.

~~(1987) 5" D.Fir now dead 7"x12' snag - scribing visible.~~

Found new BT (as of 12/2020 unrecorded 2019 BLM)

10" Fir PHDB pitched over N.77°E., 37.7 ft.

Lat: ~~43.271309937°~~ Long: ~~122.990716377°~~

43°16'16.75" -122°59'26.48"

DESTROYED BY FIRE

MMG 1145 HI=0.7835

RETAG AND REFLAG ALL REFS

5/19/21

CS 67/51-5

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T26-3

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
 (DCSO Records, Volume 10 Page 4177)

 Set post cor. to secs. 25, 36, 30 and 31, from which
 A Red Fir 26" dia., bears S.45°E., 33 lks. dist.
 A Red Fir 30" dia., bears N.22°E., 30 lks. dist.
 A Laurel 12" dia., bears S.68°W., 40 lks. dist.
 No trees convenient NW.

GLO resurvey by Charles M. Collier, Under Special
 Instructions dated May, 1913. (DCSO records, Volume 10 Pages
 4255-56)

 Cor. located by reference to the bearing trees as described
 by the surveyor general; all other traces of the cor. have
 disappeared. I re-establish this cor. in its original
 position, as follows:

Set a fir post, 3 ft. long, 4" sq. 24" in the ground, for
 cor. marked T26S S30 on NE., R2W S31 on SE., S36 on SW, and
 R3W S25 on NW faces, with 1 notch on S and 5 notches on N
 edges, witnessed by the following bearing trees:

- A Red Fir 30" dia., bears N.22°E., 30 lks. dist., marked
 T26S R2W S30 BT.
- A Red Fir 26" dia., bears S.45°E., 33 lks. dist., marked
 T26S R2W S31 BT.
- A Laurel 12" dia., bears S.68°W., 40 lks. dist., marked
 T26S R3W S36 BT.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone;
 Jerry Layne - Jan. 1966 - C.S. File 54/7-31

 Found - Orig. 26" D.Fir S.45°E., 21.8 ft. prev. opened &
 shows good "S" scribe.

No trace of SW ABT and NE BT could be rotted log
 laying in approx. location.

Set brass cap at cor. mkd: County Surveyors Office, 1966

T26S	S 25	S 30
R3W	S 36	S 31

- New BTs - 6" D.Fir N.61°E., 4.5 ft. mkd. T26S R2W S30 CS BT.
- 6" D.Fir N.5°W., 16.4 ft. mkd. T26S R3W S25 CS BT.
- 7" D.Fir S.37°W., 7.5 ft. mkd. T26S R3W S36 CS BT.

Corner found and used, BLM Dependent Resurvey, by Wayne
 Rogers, Group #1058 - June-Aug. 1981 (DCSO records, Vol.45 Pg
 17436-37)

continued next page