

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 245 RANGE 2W SEC. 10

PLSS # 460500

Date: 4/18/2022 By: JC

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 2-23-22

Map: _____

Narrative: _____

Corner Rpt: CS 67/52-23

Corner Designation

DOUGLAS COUNTY
SURVEYOR

E 1/16 S10
S15

Monument(s) Found: (Condition and Source)

___ Condition report

___ Not Found

___ Renewed

___ Unrecorded

___ Surveyed In

BLM BRASS CAP BURIED
4" IN E. EDGE OF GRAVEL ACCESS

Previous Renewals ROAD

BLM RESURVEY 1959 Vol
30 pg 12732

MONUMENT DETAIL

DCSO 1985 CS 62/29-6

E 1/16 S10
S15
1959

Accessories Found

A 15" BURNT D. FIR STUMP S41'14E 51.5 FT
HEALED SCAR

A 8" D. FIR N49'1/2W 81.9 FT Double SCAR

A 7" CEDAR S29°W 27.2 FT Double BLAZE

C.S. File 67/52-23

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Retag All Trees

Sketch of Monument, Accessories, and General Area

Location & Comments

Corner in Roadway - no GPS

NOTE: Cannot disturb ground in Arch. site
will revisit when monument can be uncovered

AREA BURNED
9-2026

Comp. Decline. 14 1/2° E
Agency DCSD
Party Chief S. Flause
Note keeper
Witnesses J. Lorusney

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1854

Expires: 12/31/2022

CS 67/52-23

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 460500

PRIMARY CORNER DESCRIPTION E 1/16 Secs. 10 & 15 VISIT 2/23/22

Alias _____	Description <u>CAN NOT DISTURB GROUND IN ARCH. SITE</u>
Alias _____	Description <u>WILL REVISIT WHEN MONUMENT</u>
Alias _____	Description <u>CAN BE UNCOVERED.</u>
Alias _____	Description _____

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12732)

Point for the E 1/16 sec. cor. of secs. 10 & 15
Set an iron post, 28" long, 2 1/2" dia., 4" below the surface of the E edge of a gravel access road, 20 lks., wide, bears NW & S curving to SE, with brass cap marked:

E 1/16 $\frac{S\ 10}{S\ 15}$
1959

from which
A fir, 9" dia., bears N.42 1/2°E., 75 lks. mkd: E 1/16 S10 BT
A fir, 10" dia. bears S.41 1/4°E., 78 lks. mkd: E 1/16 S15 BT

Douglas Co. Surveyors Office - Stephen J Flause, Party Chief - Randal W. Smith, Note keeper - 10/11/1985 - C.S. 62/29-6

Found - 1959 BLM brass cap properly marked, firmly set 7" below graveled road surface near east edge of traveled way.

Orig. 9" Fir, now a 16" dia. 6" tall fir stump with evidence of a low blaze which is opened to reveal a face and a scribed " " bears N.37°E., 49.2 ft. (Rec. N.42 1/2°E., 49.5 ft.) (Difference in bearings apparent blunder of original survey).

*BURNED STUMP
RETAG*

orig. 10" Fir, now a 15" DBH D.Fir with a fully healed single blaze bears S.41 1/4°E., 51.5 ft. as per record.

Set - Monument appears undisturbed despite slight distance error and apparent bearing blunder to original NE BT. Position of monument is accepted as found.

New BTs- A BT tag and boat spike are set at the new record bearing & distance in the NE BT stump.

*BURNED DEAD
RETAG*

An 8" DBH D.Fir, scribed E 1/16 S10 CS BT on a double blaze bears N.49 1/2°W., 81.9 ft.

*BURNED DEAD
RETAG*

A 7" DBH Incense cedar, scribed E 1/16 S15 CS BT on a double blaze, bears S.29°W., 27.2 ft.

Note: From Diamond Lake Highway (State Hwy #138) proceed NW on USFS Rd. #2-2-14, 1 + miles to Jct with USFS Rd #26-2-15. Proceed northerly along this road .5 miles to monument near private driveway and house.