

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 8W SEC. 21 PLSS # 340306

Date: 3/17/26 By: KL  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 3-12-26

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67162-21

Corner Designation

1/4 COR 521 / 528

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP  
proj 5"

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

BLM Resurvey 1962 Vol 32  
Pg 13327

MONUMENT DETAIL

1/4 521 / 528  
T24S R8W  
1962

Accessories Found

49" D. FIR S 40 1/2° E 60.2 FT (Rec S 39 1/2° E  
90 LBS) HEALED BLAZE CRUISER MARKS  
ADD 3 1/2" MAG NAIL RIGHT SIDE CENTER

BROKEN OFF 44" X 12 FT D. FIR SWAG  
N 72 1/2° W 29.0 FT FULLY HEALED SINGLE  
BLAZE

22" G. FIR FALLEN OUT OF POSITION  
FULLY HEALED SINGLE BLAZE ROOT HOLE  
NEAR HERE S 6 W 45.3 FT

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

13" G. FIR N 42° E 22.6 FT Scribed  
1/4 521 BT on Double BLAZE 3 1/2" MAG  
NAIL RIGHT SIDE CENTER

10" G. FIR N 34° W 13.3 FT Scribed  
1/4 521 BT on Double BLAZE 3 1/2" MAG  
NAIL RIGHT SIDE CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

MON ON RELATIVE EAST  
GROUND IN MIXED SECOND  
GROWTH APPROX 70 FT SOUTH  
OF GRAVEL ROAD

Comp. Decline. 14 1/4° E  
Agency DCSD  
Party Chief S. EINHUSE  
Note keeper  
Witnesses J. LORSUNG

Trimble Geo XT POSITION

43° 41188671 N

123° 65377514 W

CS 67102-21 pg 2/3

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____	Description _____
Alias _____	Description <u>TRIMBLE GEO XT POSITION</u>
Alias _____	Description _____
Alias _____	Description <u>43.46188671°N</u>
	<u>123.65377514°W</u>

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3356)

Set a post 3 1/2 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N. face, from which

A Fir 18" dia., bears N.63°W., 65 lks. dist. mkd. 1/4 S BT  
A Fir 30" dia., bears S.39 1/2°E., 90 lks. dist. mkd. 1/4 S BT.

DECLINATION 14 1/4°E

RENEWED 3/12/26

BLM resurvey by C. Albert White, Cadastral Surveyor and Donald R. Beck, Surveying Technician - under Group #427, Surveyed July/Aug. 1962 - (DCSO records Vol. 32 Page(s) 13327)

The 1/4 sec. cor., determined at record bearing and distance from the original bearing trees: 540 1/2°E 59 1/2 60 2

NOT HARD, A stump hole bears N.63°W., 65 lks. dist. ADD 3 1/2" MAG NAIL R.S.C.  
49" A Fir 40" dia., bears S. 29 1/2°E., 90 lks. dist. mkd. with a healed blaze and cruiser marks

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap mkd:

3 1/4" T 24 S R 8 W PROT 5"  
1962

from which new bearing trees

BROKEN OFF 44" X 12 FT. AD Fir 20" dia., bears N.72 1/2°W., 44 lks. dist. mkd. 1/4 S21  
S MAG BT. FHSB 29°

22" FALLEN OUT OF AG Fir 11" dia., bears S.6°W., 69 lks. dist. mkd. 1/4 S28 BT.  
POSITION FHSB 455  
ROOT HOLE NEAR HERE

NEW REFERENCES

13 " G FIR SCRIBED "1/4 S21" BT ON DOUBLE BIZ, 3 1/2" MAG NAIL R.S.C. N42°E, 22 6 FT.

10" G FIR " " " " " " " N34°W, 13 3 FT.

MONUMENT IS ON RELATIVELY FLAT GROUND IN MIXED SECOND GROWTH AND APPROX. 70 FT. SOUTH OF A GRAVEL ROAD.

MINI GIS  
43.46191  
123.65378