

SHEET 3 RECOVERED MONUMENT TABLE (FROM ST. HWY. 38-023, FILED NOVEMBER 7, 2018)

+ = MONUMENT DESTROYED BY CONSTRUCTION DRG = ODOT DRAWING

PT. NO.	STATION	OFFSET	OCRS NORTHING	OCRS EASTING	DATE	DESCRIPTION	REFERENCE DOCUMENT
1000	736+83.84	48.43	810713.95	499838.04	3/12/2015	FOUND 5/8" IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 845+28.9", GOOD CONDITION, POST AND PADDLE NEARBY "SHRP 845+28.9 50 PS"	DRG 4B-21-24
1001	737+76.08	50.00	810749.31	499922.02	3/12/2015	FOUND 1/2" HEADED NAIL IN ROCK , CENTER PUNCHED, GOOD CONDITION, POST AND PADDLE LIES ON GROUND "SHRW PC 737+75.2 50" +	DRG 4B-21-24
1002	741+00.54	49.98	810865.99	500220.11	3/12/2015	FOUND 5/8" IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. RW 741+00", GOOD CONDITION, POST AND PADDLE LIES ON GROUND "SHRW POC 741+00 50"	DRG 4B-21-24
1003	744+80.84	36.61	810982.98	500577.53	3/12/2015	FOUND 5/8" IRON ROD WITH 1 1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 853+26.33", REMNANTS OF POST AND PADDLE NEARBY.	DRG 4B-21-24
1004	745+94.61	111.02	810934.23	500702.45	3/12/2015	FOUND 5/8" SMOOTH IRON ROD, POOR CONDITION, POST AND PADDLE NEARBY MARKED "SHRW PT 745+95.20 110"	DRG 4B-21-24
1009	736+83.69	-60.91	810813.91	499793.74	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 845+28.9 L" , GOOD CONDITION, POST AND PADDLE NEARBY "SHRP PS 845+28.9 60" LEFT	DRG 4B-21-24
1010	737+76.00	-59.76	810849.70	499877.64	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP STAMPED "OREG. STATE HWY. DEPT. RW 737+75.2", GOOD CONDITION, POST AND PADDLE NEARBY "SHRW PC 737+75.2 50" LEFT	DRG 4B-21-24
1011	744+82.84	-57.79	811075.33	500557.89	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 853+26.4", GOOD CONDITION, POST AND PADDLE NEARBY "SHRP PCS L 853+26.40 55" LEFT +	DRG 4B-21-24
1012	745+95.38	-60.00	811101.96	500669.03	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 745+95.2", GOOD CONDITION, POST AND PADDLE NEARBY "SHRW PT 745+95.2 60" LEFT +	DRG 4B-21-24
1094	-	-	815580.00	506898.76	11/13/2017	FOUND 5/8" IRON REBAR WITH 1-1/2" ALUMINUM CAP "DOUGLAS CO. SURVEYOR 7, 8, 17, 18", GOOD CONDITION, WITNESS POST NEARBY	CS 67/31-11

FILED  
 Date: 2-22-2024 By: Ji  
 This survey consists of:  
 Map: St. Hwy 38-031 A-G  
 Narrative: \_\_\_\_\_  
 Corner Rpt: \_\_\_\_\_  
**DOUGLAS COUNTY**  
**SURVEYOR**

SHEET 4 RECOVERED MONUMENT TABLE (FROM ST. HWY. 38-023, FILED NOVEMBER 7, 2018)

+ = MONUMENT DESTROYED BY CONSTRUCTION DRG = ODOT DRAWING

PT. NO.	STATION	OFFSET	OCRS NORTHING	OCRS EASTING	DATE	DESCRIPTION	REFERENCE DOCUMENT
1003	744+80.84	36.61	810982.98	500577.53	3/12/2015	FOUND 5/8" IRON ROD WITH 1 1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 853+26.33", REMNANTS OF POST AND PADDLE NEARBY	DRG 4B-21-24
1004	745+94.61	111.02	810934.23	500702.45	3/12/2015	FOUND 5/8" SMOOTH IRON ROD, POOR CONDITION, POST AND PADDLE NEARBY MARKED "SHRW PT 745+95.20 110"	DRG 4B-21-24
1005	749+63.22	39.90	811077.54	501049.52	3/12/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. RW 749+63.3", GOOD CONDITION, POST AND PADDLE NEARBY "SHRP 749+63.3 BK. = PC 0+36.7 AH. EQ 40" RIGHT	DRG 4B-21-24
1006	749+63.45	-59.85	811175.27	501029.55	3/16/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 749+63.3 EQ", GOOD CONDITION, POST AND PADDLE NEARBY "SHRW 749+63.3 BK. = PC 0+36.7 AH. EQ 60" LEFT +	DRG 4B-21-24
1007	3+10.29	-39.92	811321.58	501294.88	3/16/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 3+09.1" ROD LEANS NORTHERLY 0.4 FT. POOR CONDITION POST NEARBY (NO SIGN) +	DRG 4B-21-24
1008	4+29.32	39.92	811368.41	501430.34	3/16/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP STAMP, NOT READABLE, ROD LEANS WESTERLY, POOR CONDITION, ROD TIED 2.0 FT BELOW GROUND, POST NEARBY	DRG 4B-21-24
1011	744+82.84	-57.79	811075.33	500557.89	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 853+26.4", GOOD CONDITION, POST AND PADDLE NEARBY "SHRP PCS L 853+26.40 55" LEFT +	DRG 4B-21-24
1012	745+95.38	-60.00	811101.96	500669.03	3/17/2015	FOUND 5/8" SMOOTH IRON ROD WITH 1-1/2" ALUMINUM CAP "OREG. STATE HWY. DEPT. 745+95.2", GOOD CONDITION, POST AND PADDLE NEARBY "SHRW PT 745+95.2 60" LEFT +	DRG 4B-21-24

SHEET 5 RECOVERED MONUMENT TABLE (FROM ST. HWY. 38-023, FILED NOVEMBER 7, 2018)

+ = MONUMENT DESTROYED BY CONSTRUCTION

PT. NO.	STATION	OFFSET	OCRS NORTHING	OCRS EASTING	DATE	DESCRIPTION	REFERENCE DOCUMENT
1013	11+28.21	40.00	811924.24	501851.03	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR" GOOD CONDITION	RM4-17
1014	11+81.30	75.19	811934.57	501908.52	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1015	12+11.09	82.39	811945.94	501931.78	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", FAIR CONDITION	RM4-17
1016	12+53.68	97.04	811955.60	501968.06	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1017	12+82.62	115.19	811952.92	501996.84	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1018	12+48.54	40.00	811999.42	501931.27	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION +	RM4-17
1019	13+00.39	62.66	812005.45	501982.41	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1020	13+25.02	40.09	812035.73	501991.11	3/17/2015	FOUND 5/8" IRON REBAR, POOR CONDITION, BENT TIED 1 FT BELOW GROUND	RM4-17
1021	-	-	811977.56	502104.43	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1024	14+83.41	47.49	812071.17	502130.06	3/18/2015	FOUND 5/8" IRON REBAR (NO CAP), GOOD CONDITION +	UNRECORDED
1051	14+88.42	40.11	812079.08	502133.61	3/18/2015	FOUND 5/8" IRON REBAR (NO CAP), 0.30 FT ABOVE GROUND, BENT TIED WHERE ROD ENTERS GROUND, POOR CONDITION +	RM4-17

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Andrew David Ausland*

OREGON  
 JULY 15, 2003  
 ANDREW DAVID AUSLAND  
 56136

EXPIRES: 12/31/2025

SHEET 6 RECOVERED MONUMENT TABLE (FROM ST. HWY. 38-023, FILED NOVEMBER 7, 2018)

+ = MONUMENT DESTROYED BY CONSTRUCTION

PT. NO.	STATION	OFFSET	OCRS NORTHING	OCRS EASTING	DATE	DESCRIPTION	REFERENCE DOCUMENT
1014	11+81.30	75.19	811934.57	501908.52	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1015	12+11.09	82.39	811945.94	501931.78	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", FAIR CONDITION	RM4-17
1016	12+53.68	97.04	811955.60	501968.06	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1017	12+82.62	115.19	811952.92	501996.84	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1018	12+48.54	40.00	811999.42	501931.27	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION +	RM4-17
1019	13+00.39	62.66	812005.45	501982.41	3/17/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1020	13+25.02	40.09	812035.73	501991.11	3/17/2015	FOUND 5/8" IRON REBAR, POOR CONDITION, BENT TIED 1 FT BELOW GROUND	RM4-17
1021	-	-	811977.56	502104.43	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1022	-	-	811899.12	502212.03	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1023	-	-	811941.17	502250.04	3/18/2015	FOUND 5/8" IRON REBAR WITH 1 1/4" YPC STAMPED "DOUG. CO. SUVEYOR" 0.40 FT ABOVE SURFACE GOOD CONDITION	RM4-17
1024	14+83.41	47.49	812071.17	502130.06	3/18/2015	FOUND 5/8" IRON REBAR (NO CAP), GOOD CONDITION +	UNRECORDED
1025	16+29.90	39.97	812076.14	502262.72	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1026	16+54.84	80.97	812031.67	502276.01	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1027	17+10.27	40.00	812057.48	502333.87	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1028	18+87.25	40.37	811998.06	502500.57	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1029	20+62.45	40.00	811939.92	502665.85	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1030	21+37.58	39.98	811914.87	502736.68	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1031	22+37.78	39.98	811881.43	502831.13	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1032	23+63.08	40.08	811839.52	502949.22	3/18/2015	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1041	16+22.82	67.03	812050.48	502252.09	3/18/2015	FOUND 5/8" IRON REBAR 0.40 FT ABOVE SURFACE, BENT TIED WHERE ROD ENTERS GROUND, POOR CONDITION	UNRECORDED
1051	14+88.42	40.11	812079.08	502133.61	3/18/2015	FOUND 5/8" IRON REBAR (NO CAP), 0.30 FT ABOVE GROUND, BENT TIED WHERE ROD ENTERS GROUND, POOR CONDITION +	RM4-17
1052	-	-	811881.01	502284.81	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION +	RM4-17
1053	-	-	811905.34	502393.66	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1054	-	-	811856.81	502381.20	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1055	-	-	811885.81	502461.72	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1056	-	-	811883.90	502467.73	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1057	-	-	811837.55	502446.27	8/1/2016	FOUND 5/8" IRON REBAR BENT SOUTHERLY, TIED WHERE ROD ENTERS GROUND, POOR CONDITION	RM4-17
1058	-	-	811835.81	502453.86	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1059	-	-	811835.60	502635.92	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1060	-	-	811806.65	502705.64	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1061	-	-	811758.58	502691.80	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1062	-	-	811775.89	502800.82	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17
1063	-	-	811737.15	502919.77	8/1/2016	FOUND 5/8" IRON REBAR WITH 1-1/4" YPC "DOUG. CO. SUVEYOR", GOOD CONDITION	RM4-17

OREGON DEPARTMENT OF TRANSPORTATION

RIGHT-OF-WAY BOUNDARY MONUMENTATION MAP  
 OR38: UMPQUA RIVER (SCOTTSBURG) BRIDGE REPLACEMENT  
 UMPQUA HIGHWAY (MP 15.9 - MP 17.1)  
 DOUGLAS COUNTY



ODOT REGION 3 TECH CENTER  
 100 ANTELOPE ROAD  
 WHITE CITY, OREGON 97503

KEY NO. 18578

FEBRUARY 14, 2024  
 SCALE: 1" = 50'  
 SHEET 7 OF 7

ST. HWY. 38-031 G