TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2951)

Set ¼ sec. post from which
A Fir, 72" dia., bears E. 15 lks.
A Cedar, 8" dia., bears N.50°W., 29 lks.

M.D. Hale, Weyerhaeuser Co. - 11/11/1954 - C.S. 53/111-18

Found - 72" Fir East 15 lks., scribing on bark mostly gone, Br. tag OK.
8" Cedar N.50°W., 29 lks., not chopped out, some face showing but no scribing, some scribing might be inverted on part that is grown over. Brass tag marked S.50°W., changed to S.50°E.
Cedar stake & left it for corner.
BTs - 36" Fir S.66°W., 23.6 ft. "W" nail & plate.
56" Fir N.53°W., 35.6 ft. "W" nail & plate.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Oct. 1967 - C.S. File 54/27-98

Found - 2"x20" steel pipe, bent & burned.
Orig. 72" fir, now burned stump, East 9.9 ft., no scribe, re rescribed "¼ S11 CS BT"
Orig. 8", now 14" Cedar stump, N.50°W., 19.1 ft., burned, open & find "¼" reverse, Weyerhaeuser method BT.
56" Fir now stump, N.53°W., 35.6 ft., "W" nail & tag S.W."W" BT destroyed.
Set - Brass cap at cor. mkd: County Surveyors T24S R3W Office, 1967 ¼ S 10|S 11 set in place of old pipe with 6' steel fence post alongside. No other suitable trees or stumps available. This area was clear cut & burned this yr.