TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4604)

---

Set ¼ sec. post, from which
A B.Oak 8" dia., bears S.49°W., 21 lks. dist.
A B.Oak 6" dia., bears N.45°E., 8 lks. dist.

---

Doug. County Surveyors Office - Vernon Tracy; Mike Stone, Jack Heritage - March 1966 - C.S. File 54/23-4

---

Found - Orig. 6" now 16" B.Oak N.45°E., 5.3 ft., stump cut low in B.Oak stool piece of Oak log that matches stump. We chop out "BT" & notch.
No trace of other original BT.
Set Brass cap at cor. mkd: County Surveyors Office, 1966 T26S ¼ $\frac{\text{S } 23}{\text{S } 26}$ R7W

New BTs - 10" D.Fir N.7°E., 81.5 ft. mkd. "¼ S23 CS BT".
10" D.Fir S.52½°E., 150.8 ft. mkd. "¼ S26 CS BT".
This corner lies at fence corner, fences, N-E & W. approx. 140 ft. West of top of hill.

---

Carl Sweeden -For: Rogers & Carrol - June 2000 (added to record 6/15/2020) - M135-5

---

Condition Report
Found - 2½" BC & 1¼ OD pipe per Co. Records
19" D.Fir BT, N.7°E., 81.5' healed scar & tagged
12" D.Fir BT stump, S.52°30'E., 150.80' face open w/visible scribe & tag (stump broken at 2.0' high)
16" B.Oak BT stump N.45°E., 5.30' now gone, clump of 10 B.Oak stems appears to have grown around old stump.

---

Found OK by M. Farr, April 2003 - LP 2003-0042