TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7364)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. cor., marked ¼ S on North face; from which
A fir, 13" dia., bears N.10°W., 14 lks., mkd: ¼ S BT.
A fir, 12" dia., bears S.38°W., 30 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Sept. 1965 - C.S. File 53/67-15

Found - Orig. 13" now 20" Fir N.10°W., 9.2 ft to face, shows old bark scribe "¼BT" in very poor condition.
Orig. 12" now 32" Fir S.38°W., 19.8 ft. to face, shows fragmentary bark scribe "¼S"
Set brass cap at cor. mkd: COUNTY SURVEYORS T30S R8W ¼ S 7
OFFICE 1965 S 18
New BTs- 36" D.Fir N.61°E., 13.9 ft. mkd: ¼ S7 CS BT.
13" D.Fir S.24°W., 32.9 ft. mkd: ¼ S18 CS BT.
Note - This corner lies on a NE slope of spur, course NW.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 4/16/2007 - C.S. File 67/21-26

Found - 2½" dia. brass cap, properly mkd on 1¼" O.D. IP projects 14" above ground, firmly set.
13" now 18" dia., D.Fir fully haled single blaze visible bears S.15½°W., 32.9 ft (rec S.24°W., 32.9 ft) 1965 BT - Appears 1965 crew read wrong side of compass needle?
36" now 42" dia. D.Fir snag, fully healed single blaze visible bears N.61°E. 13.1 ft (Rec. N.61°E., 13.9 ft.) 1965 BT
Both orig. trees have blown down years ago. Root holes check well for rec. bearing & dist

---