7-26-50

Section Corner 3-4-9-10, T29S, R5W, N.M. renewed by double proportionate measurement.

At corner point set 3/4 x 30" I.P. 20" in ground from which

A Cedar 16" diam. bears S37°E, 42.0' dist. mkd. S10, 2880, B.T.

A Pine 11" diam. bears N12°E 58.0' dist. mkd. S3, 2880, B.T.

A Fir 10" diam. bears N7°W 51.5' dist. mkd S4 2880, B.T.

A Fir 9" diam. bears S42W 21½' dist. mkd. S9 2880, B.T.

This corner lies near the top of Mtn. on the Northwest slope. The road is 850' North of Corner.

I doubt if this corner was ever set originally since the field notes do not check at all.

over

CS 40/259-1

There are no Oaks near
1/4 s cor. 9 + 10; 1/4 s cor. 3 + 10;
or Section cor. 3-4-9-10.
All of these corners
call for Oak B.Ts.
The feild notes call
for a creek in one chain
of Section Corner there
is no creek near this point.

John M. Mulkamp.

Witness:
Geo Vaughn.

Work done for Stamar Lbr. Co