REN. T 24 S R 7 W CC 56|55

(ON SOUTH LINE SEC. 31, T 23 S R 7 W)

FD. STUMP HOLE & PIECES OF BADLY BURNED FIR STUMP S 12° E 17 2 FT. - NO MKS. FD.

NO TRACE FD. OF S.W. B.T.

POINT FOR COR. FALLS 152 3 FT. DUE WEST OF COR. SECS. 31 & 32, T 23 S R 7 W - (GOV'T NOTES CALL FOR CLOSING COR. 2.30 CHS (151 8 FT.) WEST OF COR. SECS. 31 & 32). SINCE LOCATION IS SO CLOSE TO CALL FROM ORIG. COR., I CONCLUDE STUMP HOLE WAS S.E. B.T.

AT COR. SET IRON PIPE WITH BRASS CAP MKD. "COUNTY SURVEYOR'S OFFICE 1963 T 24 S R 7 W. CC 56|55"

BLAZE & SCRIBE NEW TREES:

18" DOUG. FIR S 20° E 11 1 FT. MKD. "T 24 S R 7 W CC S5 CSBT"

14" DOUG. FIR S 39° W 82 3 FT. MKD. "T 24 S R 7 W CC S6 CSBT"

A 3/4" IRON PIPE BEARS N 68° E 2 3 FT.

APRIL 11, 1963

M. G.
V. T.
M. S.

Mike E. Godfrey

C.S. File No. 19/44-52

Dear Mr. Milo Godfrey

Would you please search for the NW section corner common to sections 5 & 6 T24S R7W and the N¼ corner of section 5 T24S R7W. If you have time. We would appreciate the favor

David W. Taylor
forester
B.L.M.

REN. C.C. S6|S5 T 24S R7W
FROM STUMP HOLE & CALL ON
COR. SECS 31|32 (FORMERLY RENEWED)
T 23S R7W. APR. 11, 1963
Milo E. Godfrey

THE NORTH ¼ COR. OF SEC. 5, T 24S R7W
WAS NEVER SET. THE SOUTH ¼ COR.
OF SEC. 32, T 23S R7W IS AN IRON PIPE
IN AN E & W FENCE LINE. - SEE PREVIOUS
RENEWALS - (#26 & #74) RECORDED IN
T 23S R7W - NOT RECORDED IN T 24S R7W.
Milo E. Godfrey

FILED
RECEIVED
APR 8 1963
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

U. S. File No. 49|41