Renew Sec. Cors 531/532 T20S R4W Lane Co.
56/55 T21S Doug.

Fd. un Recorded 2" cast Iron pipe at
cor. Point apparently set many years
ago from Orig. B.Ts as follows-
Orig. 12" Now 14" Fir S. 14° E. 40 3/4 ft. (slope Dist.)
Now Badly decayed snag- fragmentary
scribe on upper open blaze & most of
"T" on Lower open blaze-
Orig. 20" Now 26" Fir S. 43° W. 57 1/4 ft.
Now Badly decayed stump - shows old
axe mks- No scribe Fd. - Find only
stump hole at location of N.E. O.B.T. -
No Trace Orig. N.W. - at cor set 1"
I.P. & Brass cap mkd. "Doug. Co.
Surveyors Office, 1968 T20S
531/532 56/55 T21S R4W" & mk. New B.Ts-
15" D. Fir S. 28° E. 45 8/10 ft.
mkd. "T21S R4W 55 DCS BT"
11" D. Fir S. 45° W. 42 1/10 ft.
mkd. "T21S R4W 56 DCS. BT"
24" D. Fir N. 7° W. 19 5/10 ft.
Mkd. "T20S R4W 531 DCS BT"
No Tree close To N.E. - cor. Lies
in fence Line course N. 30° E. - S 30° W.
on N.E. slope.

V.R.T.
R.W.J.

Dec. 31/1968 V.R.T. C.S. Reg. No. 1/14/42

O.K. J.W.D.

#970