FILED
Date: 3/19/2020 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: CS 65/104-61

DOUGLAS COUNTY SURVEYOR

CORNER REPORT FORM

Section 23 Township 31S Range 5W
Douglas County Date 1-2020
PLSS Number 540400

CORNER DESIGNATION

1/4 COR 14/23

- ☐ Condition Report only
- ☐ Not Found
- ☒ Renewed
- ☐ Unrecorded
- ☐ Surveyed In
- ☐ Referenced out

Previous Renewals/Surveys, etc:
King 1959 CS 42/425 BLM Resurvey 1972-73
DCSO 1966 Searched for not Fd. Vol 38 Pg 15674

Monument(s) & Accessories Found: (Condition and Source)
BLM BRASS CAP
12" FIR N30°E 28.4 FT Badly Burnt
12" FIR S12°W 25.3 FT " "

Monument Detail

Sketch

US Dept Interior
1/4 S14/S23
T31S R5W
1973
BUREAU OF LAND MANAGEMENT

Monument Set (Procedures and Description)

New Accessories
5/8" I. ROD N13°W 9.5 FT
5/8" I. ROD N28°E 13.4 FT
5/8" I. ROD S36°W 7.2 FT
5/8" I. ROD S39°E 7.8 FT

All Rod have yellow Plastic caps stamped ieengineering
5' Alum post alongside

Surveyor's Seal

Location & Comments
AREA Badly Burnt 2019

Compass Declination 15½° E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470
Party Chief: R. Heichel
Notes:
Witness: T. Ogden

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON JULY 14, 1978 RONALD A. QUIMBY 1654
EXP 12-31-20

C.S. File 65/104-61